

LOCATION: WB-9

HYDRAULIC CONDITIONS: Apparent Confined (Panther Seep Formation)

PERTINENT OBSERVATIONS: Drilled 0'-126' on 02/12/92. Drilling time increased significantly at 125'. Drilled 126'-139' on 02/14/92. Encountered limestone bedrock (Panther Seep Form) at 129'. Drilled to 380' (TD) by 02/20/92. There was no indication of significant formation water during drilling. However, when blowing hole on 02/20/92, borehole made \approx 2 gpm. By 02/21/92, water level had risen to 299.08' (TOSC). Water level had only risen to 299.06' by 02/25/92. Westbay MP System was installed 02/25/92.